



SERVICE INFORMATION

321 Records Found.

Publication Type

Pub No.	Pub Name	Date	Compliance	Title Description
SEB-28-04R2	Fuel - Placard Installation for Use of Very Low L	08/09/2023	Optional	Fuel - Placard Installation for Use of Very Low Lead and Unleaded Aviation Fuel
SEL-28-10	Fuel - Fuel Strainer Bowl Inspection	01/05/2023	Mandatory	Fuel - Fuel Strainer Bowl Inspection
SEB-28-04R1	Fuel - Placard Installation for Use of Very Low L	10/19/2021	Optional	Fuel - Placard Installation for Use of Very Low Lead and Unleaded Aviation Fuel
SE-P-003	ATA 28 - Suspected Atypical Aviation Fuel	09/04/2020	Informational	ATA 28 - Suspected Atypical Aviation Fuel
SEL-74-06R1	Ignition-Transmittal of Continental Motors SB19-0	03/24/2020	Mandatory	Ignition-Transmittal of Continental Motors SB19-02A, Lycoming SB637, and Champion Aerospace Slick Service Bulletin SB1-19
SEL-61-01	Propeller - Propeller Governor Inspection In Acco	11/16/2018	Mandatory	Propeller - Propeller Governor Inspection In Accordance with McCauley ASB273
SEL-71-07	Powerplant - Transmittal of Lycoming SB No. 632A	07/24/2017	Mandatory	Powerplant - Transmittal of Lycoming Service Bulletin No. 632A Identification of Connecting Rods with Non-Conforming Small End Bushings
SE-P-001	ATA 00 - Textron Aviation Piston Aircraft Technic	02/01/2017	Informational	ATA 00 - Textron Aviation Piston Aircraft Technical Support
SEL-74-04	Ignition - Transmittal of Continental Motors Ser	11/14/2016	Informational	Ignition - Transmittal of Continental Motors Service Bulletin SB15-5 and Lycoming Service Letter No. L264A

Pub No.	Pub Name	Date	Compliance	Title Description
SEL-99-01	Incremental Library Updates For Cesview	01/29/2016	Informational	Incremental Library Updates For Cesview
SEB07-5R06	Pilot and Copilot Secondary Seat Stop Install	06/11/2015	Mandatory	Pilot and Copilot Secondary Seat Stop Installation
SEL-25-03R1	Equipment/Furnishings - Pilot and Copilot Seconda	04/28/2015	Mandatory	Equipment/Furnishings - Pilot and Copilot Secondary Seat Stop Installation - Reel Assembly Inspection
SEL-20-01R1	Standard Practices - Listing of Nondestructive Te	10/22/2014	Informational	Standard Practices - Listing of Nondestructive Testing Facilities
SEL-24-03	Transmittal of HET Service Bulletin No. 053	09/12/2013	Recommended	Transmittal of HET Service Bulletin No. 053
SEL-05-01-R01	Continuing Airworthiness Program Structural Inspe	11/14/2012	Informational	Continuing Airworthiness Program Structural Inspections Supersedure
SEB-27-01-R02	Control Column Internal Glide Attach Screw Instal	04/20/2012	Mandatory	Control Column Internal Glide Attach Screw Installation
SEB11-4-R01	Roller Housing Inspection	01/20/2012	Recommended	Roller Housing Inspection
SNL11-29	Cessna Service Document Change Notification	11/22/2011	Informational	Cessna Service Document Change Notification
SEB11-3	Dual Magneto Attachment Inspection	05/24/2011	Recommended	Dual Magneto Attachment Inspection
SNL11-8	Engine Inspection in Particulate-Laden Environmen	04/26/2011	Not Applicable	Engine Inspection in Particulate-Laden Environments (Volcanis Ash, Sand, Dust, Airborne Debris)
SEB11-2	Main Landing Gear Steel Pivot Assembly Inspection	04/26/2011	Recommended	Main Landing Gear Steel Pivot Assembly Inspection
SNL11-4	Magneto Drop-Off	03/22/2011	Not Applicable	Magneto Drop-Off
SK210-174B	Pilot Secondary Seat Stop Installation	06/15/2010	Not Applicable	Pilot Secondary Seat Stop Installation
SK210-175A	Copilot Secondary Seat Stop Installation	06/15/2010	Not Applicable	Copilot Secondary Seat Stop Installation
SNL10-5	Ethanol Based Fuel Not Approved For Use In Cessna	05/18/2010	Informational	Ethanol Based Fuel Not Approved For Use In Cessna Airplanes

Pub No.	Pub Name	Date	Compliance	Title Description
SEB10-1	Pilot and Copilot Secondary Seat Stop Installatio	03/15/2010	Mandatory	Pilot and Copilot Secondary Seat Stop Installation - Reel Assembly Inspection
SEB09-6-R01	Electrical Switches Inspection and Replacement	11/23/2009	Mandatory	Electrical Switches Inspection and Replacement
SEB00-5-R03	Cleveland Wheels and Brakes Installation	10/26/2009	Recommended	Cleveland Wheels and Brakes Installation
SK182-120D	Cleveland Wheels and Brakes Installation	10/26/2009	Not Applicable	Cleveland Wheels and Brakes Installation
SK210-173A	28-Volt Starter Contactor Replacement	10/01/2009	Not Applicable	28-Volt Starter Contactor Replacement
SEB09-4	Carburetor Float Replacement - Lycoming Engine Ai	04/27/2009	Mandatory	Carburetor Float Replacement - Lycoming Engine Airplanes
SEB08-5	Alternate Static Source Selector Valve Inspection	10/13/2008	Mandatory	Alternate Static Source Selector Valve Inspection
SEB07-10	Incorrect Cylinder Assy Shipped w/Cylinder Kits	11/19/2007	Mandatory	Re-transmitting Lycoming's Mandatory Service Bulletin to inspect for installation of incorrect cylinder kits being installed on Cessna airplanes.
SEB07-9	Gray Tinted Side and Aft Windows Availability	11/05/2007	Optional	To announce that gray tinted side and aft cabin windows are available to replace existing windows.
SK210-177	Pilot Secondary Seat Stop Installation - Reel Asm	09/10/2007	Not Applicable	Pilot Secondary Seat Stop Installation - Reel Assembly Replacement
SK210-178	Copilot Secondary Seat Stop Installation - Reel A	09/10/2007	Not Applicable	Copilot Secondary Seat Stop Installation - Reel Assembly Replacement
SEB07-8	Secondary Seat Stop Install - Reel Assy Inspect	09/10/2007	Mandatory	It has been determined that some secondary seat stop 505590-401 Reel Assemblies may not always operate correctly and must be replaced as described in this Service Bulletin. Non-compliance with this Service Bulletin could allow the continued use of an inoperative secondary seat stop reel assembly.

Pub No.	Pub Name	Date	Compliance	Title Description
SEB07-6	Elevator Trim Tab Actuator Assy Inspection	08/13/2007	Mandatory	One report has been received of sheared groove pins on an elevator trim tab actuator chain sprocket. It has been determined that the affected elevator trim tab actuators shall have the groove pins replaced and the actuator assembly inspected as described in SEB07-6. Non-compliance with SEB07-6 could allow the elevator trim tab actuator chain sprocket to come loose.
SEB01-2R2	SEB01-2 Rev.2, Main Landing Gear Actuator Inspect	06/04/2007	Mandatory	To remove all model 182R and T182 airplane serial numbers from the Effectivity section. Also, to remove model 210 airplane serial numbers 57001 through 21057840, 616, & 618 from the Effectivity section. To add additional actuator assembly part numbers to the Material section and miscellaneous changes as required.
SEB06-1R1	Gray Tinted Windshield Availability	05/21/2007	Optional	To include additional windshield part numbers and airplane applicability to the Material section.
SEB07-3	Main Landing Gear Actuator Hydraulic Line Inspec.	04/16/2007	Recommended	A report was received of attach screws being installed incorrectly on the main landing gear (MLG) actuator access panel. The incorrectly installed attach screws caused wear and damage to a MLG hydraulic actuator line located under the access panel. This Service bulletin provides an inspection of the access panel attach screws and the hydraulic lines. Non-compliance with this Service Bulletin could result in possible damage to the MLG hydraulic actuator lines and the potential to loose hydraulic pressure to the MLG actuator.
SNL07-9	Maintaining Current Service and Operational Info.	04/16/2007	Informational	The purpose of this Service Newsletter is to inform Cessna Customers of the various options available to assist them in maintaining the currency of publications utilized for maintenance and operation of Cessna Propeller airplanes.
SNL06-18	FAA-Approved Deicing Updates - Winter 2006/07	12/26/2006	Informational	This Service Newsletter provides notification that Federal Aviation Administration (FAA) Notice Number N 8000.329: FAA - Approved Deicing Program Updates, Winter 2006 - 2007 has been issued.

Pub No.	Pub Name	Date	Compliance	Title Description
SNL06-17	New ELT Placards	12/18/2006	Informational	The purpose of this Service Newsletter is to provide notification that new ELT placards are available. The new placards have been updated to state the current FAA regulation for servicing the ELT. FAA Regulation 91.52 no longer exists, and has been superseded by 14 CFR Part 91.207.
SEB06-5	Electrical Ground Strap Inspection	09/11/2006	Mandatory	It has been determined that some electrical ground straps may not have been manufactured correctly. The ground straps shall be inspected and if necessary, replaced as described in this Service Bulletin. Non-compliance with this Service Bulletin could allow corrosion to form on the ground strap and adjacent attachment points and potentially affect the performance of the electrical and avionics systems and related components.
SEB06-2R1	Engine Crankshaft Retirement	05/08/2006	Mandatory	SEB06-2 Revision 1 has been issued to transmit Lycoming Mandatory Service Bulletin No. 569A: Crankshaft Retirement For Certain Lycoming Engines. According to Lycoming; Lycoming has continued to analyze crankshafts in service. While there have been no failures in the crankshafts, which are the subject of Lycoming Mandatory Service Bulletin No. 569A, as part of Lycomings' commitment to quality, they are initiating a crankshaft retirement program. This crankshaft retirement program requires the removal of the subject crankshafts when the crankcase is separated or at overhaul, whichever occurs first, not to exceed February 21, 2009.
SNL06-9	Approval of Diethylene Glycol Monomethyl Fuel Add	04/24/2006	Informational	The purpose of this Service Newsletter is to provide notification that the use of DIEGME or DEGMME fuel additive is an acceptable substitute for the affected airplanes that have previously been approved for the use of EGME fuel additive.
SNL06-8	Propeller Blade Leak Troubleshooting Instructions	04/10/2006	Informational	The purpose of Service Newsletter SNL06-8 is to provide assistance in identifying and assessing propeller oil leaks and determining the necessary corrective action.

Pub No.	Pub Name	Date	Compliance	Title Description
SEB06-2	Engine Crankshaft Retirement	03/27/2006	Mandatory	Service Bulletin SEB06-2 has been issued to transmit Lycoming Mandatory Service Bulletin No. 569: Crankshaft Retirement For Certain Lycoming Engines. According to Lycoming; Lycoming has continued to analyze crankshafts in service. While there have been no failures in the crankshafts, which are the subject of Lycoming Mandatory Service Bulletin No. 569, as part of Lycomings' commitment to quality, they are initiating a crankshaft retirement program. This crankshaft retirement program requires the removal of the subject crankshafts when the crankcase is separated or at overhaul, whichever occurs first, not to exceed February 21, 2009.
SNL06-5	Maintaining Current Service and Operational Info.	03/20/2006	Informational	The purpose of this Service Newsletter is to inform Cessna Customers of the various options available to assist them in maintaining the currency of publications utilized for maintenance and operation of Cessna Propeller airplanes.
SNL06-6	FAA Approved Supplemental Type Certificates	03/20/2006	Informational	In response to customer inquiries, Cessna is providing this SNL06-6 to provide guidance to our customers regarding the incorporation of STC's and/or PMA approved parts that have not been evaluated by Cessna. Some examples of modifications and parts that may affect the airplane aerodynamics, gross weight, flying characteristics, structure, systems or performance are: powerplant and propeller changes, add-on wing tip fuel tanks, vortex generators, camera modifications, winglets, oversize tires, etc.
SEB06-1	Gray Tinted Windshield Availability	02/27/2006	Optional	SEB06-1 has been issued to announce that gray tinted windshields are available to replace existing windshields.
SEB05-3R1	Engine Crankshaft Replacement	12/12/2005	Mandatory	To transmit Lycoming Mandatory Service Bulletin No. 566 Supplement No. 1.
SNL05-16	FAA- Approved Deicing Program Update	11/21/2005	Informational	To announce FAA Flight Standards Information Bulletin FSAT 05-02: FAA - Approved Deicing Program Updated, Winter 2005 - 2006.
SEB05-6	Vacuum Pump Inspection/ Replacement	10/31/2005	Mandatory	To transmit Tempest Mandatory Service Bulletin Number SB-003: Vacuum Pump Replacement.

Pub No.	Pub Name	Date	Compliance	Title Description
SEB01-5R1	Engine Driven Fuel Pump Inspection	10/10/2005	Mandatory	To transmit Lycoming Mandatory Service Bulletin No. 548A: Diaphragm-Type Fuel Pump Inspection/ Replacement.
SEB05-3	Engine Crankshaft Replacement	07/18/2005	Mandatory	To transmit Lycoming Mandatory Service Bulletin No. 566; Crankshaft Replacement in Lycoming Engines.
SNL05-4	FAA - Approved Deicing Program Update	03/14/2005	Informational	To announce FAA Flight Standards Information Bulletin FSAT 04-05: FAA - Approved Deicing Program Updated, Winter 2004 - 2005.
SNL05-2	Handling of Airplane Gyro Instruments	01/31/2005	Informational	Maintenance Practices - Handling of Airplane Gyro Instruments.
SEB04-4	Fuel Hose Inspection	09/13/2004	Mandatory	To inspect and verify approved fuel hose installed.
SNL04-5	FAA Approved Supplemental Type Certificates	05/31/2004	Informational	FAA Approved supplemental type certificates (STC's) and FAA-PMA approved parts
SNL03-10	Handling of Airplane Gyro Instruments	10/27/2003	Informational	To transmit gyro handling guidelines set out in Honeywell Service Memo No. 377.
SEB00-8R2	Engine Oil Filter Converter Plate Gasket Replace	10/13/2003	Mandatory	Transmits Supplement No. 1 To Textron Lycoming Msb 543A
SEB03-1	Elevator Rivet Installation	01/20/2003	Mandatory	To enhance the service life of the elevators by increasing the size of eight rivets and installing four additional rivets in the outboard elevator rib.
SNL02-6	Ethanol Based Fuel Not Approved For Use	09/16/2002	Informational	The use of Ethanol based fuels in any Cessna manufactured piston engine powered airplane has not been and continues not to be approved by Cessna.
SEB02-2	Flammable Fluid Lines Inspection	02/18/2002	Mandatory	Inspection of all flammable fluid carrying hoses/lines and oxygen lines in the cabin is required.
SEB02-3	Dry Vacuum Pump & Coupling Replacement	02/18/2002	Mandatory	To provide replacement time requirements for engine driven dry vacuum pumps, electric standby vacuum pumps and vacuum pump drive couplings.
SEB01-2R1	SEB01-2 Rev.1, Main Landing Gear Actuator Inspect	09/17/2001	Mandatory	Inspection is required of the main landing gear actuators for the presence of cracks. Cracked actuators and actuator bodies shall be replaced.

Pub No.	Pub Name	Date	Compliance	Title Description
SEB95-3R1	Flap Support Inspection & Roller Washer Install.	09/17/2001	Mandatory	Service experience indicates potential for wearing of the flap supports by the flap rollers. Inspection of the flap supports & rollers along with modification to install stainless steel washers on each side of the forward rollers shall be accomplished.
SEB01-6	Ignition Switch Center Ground Terminal Inspection	06/25/2001	Recommended	Inspect Ignit. Switch Board And Replace If Required
SEB01-5	Engine Driven Fuel Pump Inspection	05/28/2001	Mandatory	To Transmit Lycoming Mandatory Service Bulletin No. 548
SEB99-18R1	Fuel Quantity Indicating System Inspection	04/30/2001	Mandatory	To Verify Gauge Reads Empty When Tanks Are Empty
SEB01-2	Main Landing Gear Actuator Inspection	02/19/2001	Mandatory	Inspection Of Main Landing Gear Actuator For Cracks
SNL00-14	Cessna Service Information For Propeller Models	12/26/2000	Optional	To Provide Description Of Service Information Offered
SEB00-7	Vacuum System Air Filter Element Inspect/Replace	09/11/2000	Mandatory	Inspection For Airborne Air Filter Element Spec. In Bulletin
SNL00-11	Approved Nondestructive Testing Facilities (NDT)	08/28/2000	Informational	To Provide A Listing Of Ndt Facilities
AQK182-012A	Firewall Forward Engine Hose Kit	05/05/2000	Not Applicable	Firewall Forward Engine Hose Kit (for aircraft with SK182-67)
SK182-101B	Seat Belt And Shoulder Harness Kit Installation	05/05/2000	Not Applicable	Seat Belt And Shoulder Harness Kit Installation
AQK182-012	Firewall Forward Engine Hose Kit	05/05/2000	Not Applicable	Firewall Forward Engine Hose Kit (for aircraft without SK182-67)
SEB00-2	Teledyne Continental Ignition Systems Magneto	04/24/2000	Mandatory	To Transmit Textron Lycoming Service Bulletin No. 541
SEB99-16R1	Vacuum System Manifold Check Valve Inspection	04/24/2000	Mandatory	To Provide Inspection For Vacuum System
SNL00-02	Service Publications Temporary Revision Changes	01/17/2000	Informational	To announce changes for temporary revisions

Pub No.	Pub Name	Date	Compliance	Title Description
SK207-20	Cablecraft Friction Cone Washer Installation	11/17/1999	Not Applicable	Cablecraft Friction Cone Washer Installation
SNL99-12	Cablecraft Engine Control Cable Friction Cone	11/15/1999	Informational	Prevents Slippage After Friction Lock Has Been Applied
SNL99-14	Maintenance Practices - Airplane Gyro Instruments	11/15/1999	Optional	Gyro Handling Procedures
SEB99-17	Engine Valve Seat Inspection	11/01/1999	Mandatory	Transmits Textron Lycoming Mandatory Service Bulletin 540
SEB99-13	Oxygen Gage Support Modification	09/13/1999	Optional	To Announce Availability Of A Service Kit For Oxygen Gage
SK210-162	Oxygen Gage Support Modification	09/13/1999	Not Applicable	Oxygen Gage Support Modification
SEB92-21R1	Lycoming Proc. To Determine Exhaust Valve & Guide	06/01/1999	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 388B
SEB99-05	Wing Fuel Tank Vent Check Valve Inspection	04/26/1999	Mandatory	Inspect For S2359-1 Check Valve To Ensure Nonobstruction
SEB99-01R1	Engine Piston Pin Plug Wear Inspection	04/05/1999	Recommended	Transmits Several Textron Lycoming Service Issues
SNL98-11	Year 2000 Readiness Disclosure	12/21/1998	Informational	Addresses Readiness Of Year 2000 For Various Systems
SNL98-12	Year 2000 Calendar Preparation	12/21/1998	Informational	Year 2000 Calendar Preparation
SEB98-09	Airborne Vacuum Pump Inspection	11/02/1998	Mandatory	Transmit Airborne Air & Fuel Products Service Letter #48
SNL98-08R1	Revised Maintenance Practices - Hazardous Air	11/02/1998	Informational	Replace Pages 1 And 2 Of SNL98-8
SNL98-09R1	New Pilot Safety And Warning Supplements	10/26/1998	Informational	Announce New Pilot Safety & Warning Supplement D5139-13
SNL98-10	Cessna Service Information For Propeller Models	09/14/1998	Informational	Brief Description Of Service Information Issued By Cessna

Pub No.	Pub Name	Date	Compliance	Title Description
SNL98-08	Revised Maintenance Practices - Hazardous Air	07/20/1998	Informational	Refer To Federal Register, 40 Code Of Fed. Reg. Part 63
SNL98-07	Approved Nondestructive Testing Facilities	06/29/1998	Informational	This Service Newsletter Supersedes SNL95-8
SNL98-03	Cessna Customer Care Supplies And Pubs Catalog	04/27/1998	Informational	1998 Cessna Customer Care Sup. & Pubs. Catalog (D7512-13)
SEB98-01	Magneto Distributor Gear Maintenance	02/02/1998	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin No. 528
SEB97-09	Fuel Strainer Assembly Inspection	11/17/1997	Mandatory	Inspect 0756005-2/-8/-9 Shipped From Cessna 12/12/96 & 9/5/97
SEB97-07R1	Stall Warning Ground Modification	11/03/1997	Recommended	Re-route, Bond, Check Grd. Connection For Stall Warning Vane
SEB92-11R1	Textron Lycoming Mandatory Replace of Parts	11/03/1997	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 240N
SK210-159A	Stall Warning Ground Modification	09/15/1997	Not Applicable	Stall Warning Ground Modification
SNL97-03	New Cessna Service Station Directory	04/18/1997	Informational	Announces P/N D7540-13 Directory (Dated January 1997)
SEB97-02	Magneto Impulse Coupling Spring Replacement	03/24/1997	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 526
SNL97-02	Cessna Customer Care Supplies And Pubs Catalog	03/17/1997	Informational	1997 Cessna Customer Care Supp. & Pubs. Catalog (D7501-13)
SK182-117	Engine Mixture Control Assembly Replacement	01/01/1997	Not Applicable	Engine Mixture Control Assembly Replacement
SEB96-15	S51-10 Hose Inspection/ replacement	10/18/1996	Mandatory	S51-10 Hose Shipped From CPD 3/28/95-6/28/96 May Deteriorate
SNL96-03	New Cessna Service Station Directory	08/09/1996	Informational	Announces P/N D7494-13 Directory (Dated May 1996)
SEB96-07	AN3-5A Bolt Inspection/ replacement	05/10/1996	Recommended	Bolts Shipped 8/2/94-4/6/95 Do Not Meet Shear Strength Spec.

Pub No.	Pub Name	Date	Compliance	Title Description
SNL96-02	Cessna Prop. Aircraft Product Support Brochure	04/19/1996	Informational	Cessna Propeller Aircraft Product Support Brochure D7492-13
SEB96-02	Seat Belt & Shoulder Harness Connection Inspec.	03/29/1996	Mandatory	To Obtain Proper Shoulder Harness/seat Belt Connection
SK182-115	Lower Forward Bulkhead And Wing Strut Fitting	12/29/1995	Not Applicable	Lower Forward Bulkhead And Wing Strut Fitting
SEB95-20	Nose Landing Gear Actuator Downlock Pin Inspec	12/29/1995	Recommended	Determine The Security Of The Actuator Downlock Pins
SK210-155	Downlock Actuator Pin Replacement	12/29/1995	Not Applicable	Downlock Actuator Pin Replacement
SEB95-19	Lower Forward Doorpost And Strut Fitting Inspec	12/29/1995	Mandatory	Inspect For Cracks In Lower Area Of Forward Cabin Doorposts
SNL95-10	Cessna Customer Care Supplies And Pubs Catalog	12/29/1995	Informational	1996 Cessna Customer Care Supp. & Pubs. Catalog (D7480-13)
SNL95-09	FAA Apv'd Supp Type Cert (STC's) & FAA-PMA Apv'd	11/17/1995	Informational	FAA Responsible For Aftermarket STC & PMA Components
SNL95-08	Approved Nondestructive Testing Facilities	09/01/1995	Informational	Cessna Certified Nondestructive Testing Facilities
SNL95-04	New Cessna Service Station Directory	07/14/1995	Informational	Announces P/N D7479-13 Directory (Dated March 1995)
SNL95-03R1	Engine Connecting Rod Bolt Inspection	03/31/1995	Informational	Revise Affected Models To Include 172RG Model Airplanes
SEB95-04	Lycoming Engine Inspection Of Thermostatic Bypass	03/24/1995	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 518A
SEB95-06	Engine Rubber Fuel Hose Inspection & Replacement	03/24/1995	Mandatory	Replace Aeropquip 601 Type Hose With Teflon Type Fuel Hose
SK180-44	Flap Support And Flap Roller Washer Installation	03/10/1995	Not Applicable	Flap Support And Flap Roller Washer Installation
SEB95-03	Flap Support Inspection & Roller Washer Install.	03/10/1995	Recommended	Install Stainless Steel Washers On Each Side Of Fwd. Rollers

Pub No.	Pub Name	Date	Compliance	Title Description
SNL95-01	Cessna Customer Care Supplies And Pubs Catalog	01/20/1995	Informational	1995 Cessna Customer Care Supp. & Pubs. Catalog (D7469-13)
SNL95-02	Continued Airworthiness Program	01/20/1995	Recommended	Specifies Additional Inspections Which Should Be Performed
SNL94-13	Revised Progressive Care & Continuous Inspec.	12/30/1994	Informational	Revision 4 Plus Information For Developing Insp. Programs
SEB93-16R1	Prop Gov Flyweight Assy & Pilot Spool End Fitting	12/16/1994	Mandatory	Reference Mccauley Alert Service Bulletin 214
SEB93-17R1	Pitot Heater Operation Warning Placards	12/16/1994	Mandatory	Rev. Effectivity Sect. To Include Additional Serial Numbers
SEB94-18	Improved Retaining Method For Carburetor Mixture	07/15/1994	Mandatory	Transmit Precision Airmotive Corp. Mandatory Bulletin MSA-6
SEB94-16	Eng Cylinder Head Temp Gauge & Sending Unit Rep	07/15/1994	Recommended	Replace Stewart Warner Components With Rochester Components
SK182-107	Fuel Quantity Gauge and Transmitter Replacement	07/15/1994	Not Applicable	Fuel Quantity Gauge and Transmitter Replacement
SEB94-17	Engine Oil Temperature Gauge And Sending Unit Rep	07/15/1994	Recommended	Replace Stewart Warner Components With Rochester Components
SEB94-15	Fuel Quantity Gauge And Transmitter Replacement	07/15/1994	Recommended	Replace Stewart Warner Components With Rochester Components
SK182-109	Cylinder Head Temperature Gauge And Sending Unit	07/15/1994	Not Applicable	Cylinder Head Temperature Gauge And Sending Unit Replacement (For Airplanes Having A 24 Volt Electrical System)
SNL94-08	New Cessna Service Station Directory	07/01/1994	Informational	Announces P/N D7467-13 Directory (Dated May 1994)
SEB94-13	Lycoming Engine Shroud Tube Retaining Spring	07/01/1994	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin No. 519
SEB92-06R1	Magneto Impulse Coupling And Stop Pin Inspection	05/27/1994	Mandatory	SEB92-6 Is Superseded By Service Bulletin SEB94-9
SEB94-09	Inspection Of Riveted Impulse Couplings And Stop	05/27/1994	Mandatory	This Bulletin Supersedes SEB92-6

Pub No.	Pub Name	Date	Compliance	Title Description
SNL94-06	Propeller Airplanes Serial Number Listing	05/20/1994	Informational	Revised Serial Number Listing Replaces SNL87-26
SNL94-04	Cessna Service Information For Propeller Models	04/29/1994	Informational	Types Of Service Information Being Issued By Cessna
SNL93-10	Cessna Customer Care Supplies And Pubs Catalog	12/30/1993	Informational	1994 Cessna Customer Care Supplies And Publications Catalog
SEB93-20	Insp. Of Lyc. Eng. Connect. Rods For Fretting	12/23/1993	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 439A
SNL93-09	Field Inspection And Repair Of Mccauley Propeller	12/10/1993	Informational	Repairs To Obtain Optimum Service Life Of Mccauley Propeller
SNL93-06	Maintenance Practices For Pressure Cylinders	09/17/1993	Informational	FAA Order 8000.40C On Maintenance Of Pressure Cylinders
SEB93-12	Crankshaft Gear Mod & Assembly Procedures	07/30/1993	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 475B
SEB93-11	Insp & Straighten of Bent Crankshaft Flanges	07/30/1993	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 201E
SNL93-04	New Cessna Service Station Directory	07/16/1993	Informational	Announces P/N D7454-13 Directory (Dated May 1993)
SEB93-06	Magneto Impulse Coupling Installation Procedures	06/25/1993	Mandatory	Transmit TCM Bulletin M93-10 & TCM Ignition Bulletin No. 639
SNL93-03	Cabin Skin Panel Corrosion Inspection And Repair	06/25/1993	Informational	Repair Corrosion Damage Under Vibration Damping Material
SNL92-08	Cessna Customer Care Supplies And Pubs Catalog	12/31/1992	Informational	1993 Cessna Customer Care Supplies And Publications Catalog
SNL92-07	Approval Of Slick 4300 And 6300 Series Magnetos	10/09/1992	Informational	Ref. Slick Form L-1058-H, Textron Serv. Instr.1374B Or 1443A
SEB92-29	Ignition Switch Inspection	10/09/1992	Mandatory	Transmit TCM Mandatory Service Bulletin No. 636
SEB89-02R2	Pilot Seat Secondary Stop Installation	09/04/1992	Mandatory	Superseded by SEB07-5R06
SK172-94D	Secondary Seat Stop - (Pilot)	09/04/1992	Not Applicable	Secondary Seat Stop - (Pilot)

Pub No.	Pub Name	Date	Compliance	Title Description
SE84-16R2	Fuel Filler Diameter Mod & External Turbo Placard	09/04/1992	Recommended	This Service Letter Is Superseded By SEB92-27
SEB92-28	Seat Belt And Shoulder Harness Installation	09/04/1992	Mandatory	Provide Metal-to-metal Connection Type Assemblies
SEB92-27	Reduced Dia Vented Fuel Cap Instl & Turbo Placard	09/04/1992	Mandatory	This Bulletin Supersedes SE77-6/-6 Rev.1, SE84-16/-16 Rev.1
SK182-85B	Reduced Diameter Fuel Cap Mod (Bladder Fuel Cell)	09/04/1992	Not Applicable	Reduced Diameter Fuel Cap Modification (Bladder Fuel Cells)
SEB92-21	Lycoming Proc. To Determine Exhaust Valve & Guide	08/14/1992	Mandatory	Transmit Textron Lycoming Mandatory Service Bulletin 388B
SNL92-04	New Cessna Service Directory	07/10/1992	Informational	Announces P/N D7437-13 Directory (Dated June 1992)
SEB92-04	Carburetor Composite Float Replacement	02/28/1992	Mandatory	Precision Airmotive Mandatory Service Bulletin MSA-1 Rev. 1
SNL92-01	Cessna Customer Care Supplies And Pubs Catalog	01/17/1992	Informational	1992 Cessna Customer Care Supplies And Publications Catalog
SNL91-05	Temporary Revisions To Maintenance Manuals & Part	12/13/1991	Informational	Temporary Revisions For Paper & Aerofiche In Paper Form Only
SNL91-03	New Cessna Sales And Service Directory	07/26/1991	Informational	Announces P/N D7427-13 Directory (Dated May 1991)
SEB91-05R1	Ignition Switch Lubrication & Starter Contactor	06/14/1991	Recommended	Correct Serial Effectivity And Accomplishment Instructions
SNL90-13	Cessna Customer Care Supplies And Pubs Catalog	12/21/1990	Informational	1991 Cessna Customer Care Supplies And Publications Catalog
SNL90-06	Champion Oil Filter Recall	09/21/1990	Informational	Review TCM Service Bulletin M90-14 And Champion Alert 90-1
SNL90-05	New Cessna Sales And Service Directory	06/22/1990	Informational	Announces P/N D7409-13 Directory (dated May 1990)
SNL89-16	Customized Service Bulletin Listing Program	12/29/1989	Informational	Provides List Of All S/B's Applicable To Your Airplane

Pub No.	Pub Name	Date	Compliance	Title Description
SNL89-19	Cessna Customer Care Supplies And Pubs Catalog	12/08/1989	Informational	P/N D7407-13 (1990) Now Available - (supersedes SNL88-15)
SNL89-15	Production Change For Aerofiche Publications	09/22/1989	Informational	All Future Aerofiche Production Will Be In Negative Format
SNL89-14	Revised Progressive Care & Continuous Inspection	09/15/1989	Informational	Announces P/N D5552-2-13 Operations Manual
SK182-87B	Electrical Standby Vacuum Pump System-28 Volt	05/05/1989	Not Applicable	Electrical Standby Vacuum Pump System-28 Volt
SK172-102A	Secondary Seat Stop - Standard Seat (Pilot)	04/14/1989	Not Applicable	Secondary Seat Stop - Standard Seat (Pilot)
SNL89-05	Propeller Aircraft Special Tools Catalog	03/31/1989	Informational	This Publication Supersedes P/N D5487-13 And P/N D5510-13
SK188-75A	RH Rear Spar Splice-(Inboard of Wing Sta. 56.5I)	02/16/1989	Not Applicable	RH Rear Spar Splice-(Inboard of Wing Sta. 56.5I)
SNL88-12	Importance of Pilot Seat Security, Inspec & Maint	08/05/1988	Informational	Stresses The Importance Of Inspection And Maintenance
SNL88-06	Revised Progressive Care & Continuous Inspection	03/25/1988	Informational	This Publication Superseded By SNL89-14
SEB88-01	Upper Strut Cuff Seal Installation	02/26/1988	Recommended	Install Seal At Intersection Of Strut And Upper Strut Cuff
SNL87-27	Revision Status Checklist Cards For Technical Pub	11/13/1987	Informational	Also Includes Order Form P/N D5573-13
PNL87-14	S2275 Series Seat Belts	10/12/1987	Not Applicable	S2275 Series Seat Belts
SK188-31D	LH Rear Spar Splice - (Inbd of Wing Sta. 56.531)	10/09/1987	Not Applicable	LH Rear Spar Splice - (Inbd of Wing Sta. 56.531)
SEB86-05R1	Special 'Seat Locked & Fuel Contamination' Warn	08/28/1987	Mandatory	Placards Sent To All Registered Owners
SEB87-07	Propeller Governor Pilot Spool Fitting & Flyweigh	08/28/1987	Recommended	Improved Prop Gov Pilot Spool End Fitting-replace Flyweights
SEB87-04	Aileron Hinge Inspection	06/12/1987	Recommended	Applies if 0523816-1 Hinges were Installed I/A/W SE84-22

Pub No.	Pub Name	Date	Compliance	Title Description
SK182-80A	R182 Downlock Switch Relocation	04/01/1987	Not Applicable	R182 Downlock Switch Relocation
SNL87-10	Cessna Propeller Aircraft Technical Support	03/13/1987	Informational	Announces Extensive Network Of People/facilities & Resources
SNL85-03R2	A/C Windshield & Window Maintenance Procedure	03/06/1987	Informational	Maintenance And Cleaning Procedures For Acrylic Windshields
SNL86-49	Main Landing Gear Actuator Mount Bolt Security	12/12/1986	Informational	Drilled Head Bolt, AN175h22A Is An Approved Alternate
SNL86-44	Flight Control Surface Balancing Information	09/12/1986	Informational	Supplemental Info & Detailed Info On Use Of Balance Fixture
SNL86-39	Phillips X/C II Multiviscosity Oil	09/05/1986	Informational	Phillips X/C II Oil Does Not Qualify To Mil Specification
SNL86-32	Progressive Care Inspection Schedules	07/25/1986	Informational	New Progressive Inspection Schedules Now Available
SEB86-01R1	Downstop Pad Improvement	05/16/1986	Optional	Incorporates Solid Metal Downstop Pad For Improved Serv Life
SNL86-06R1	Slick Master Service Manual Availability	02/21/1986	Informational	Announces New Slick Master Service Manual P/N F-1100
SNL85-58	Use Of Overhauled/ Reconditioned Dry Vacuum Pump	12/20/1985	Informational	Airborne Service Letter No. 29 Attached
SNL85-53	Cessna Pilot Safety And Warning Supplements	11/27/1985	Informational	Provides P/N D5099-13 Safety And Warning Supplement
SNL85-54	Revised O/H-replacement Req. For Hydraulic System	11/27/1985	Informational	Specific Items Revised To 'on Condition' Overhaul Interval
SNL85-51	New Cessna Aircraft Condition Report Form	11/15/1985	Informational	P/N D5537-13 Form (P/N D5537-1-13 Available 1-1-89)
SEB85-18	Standby Electric Vacuum Pump Installation	11/08/1985	Optional	Mod Kits For Installing Electric Driven Standby Vacuum Pump
SNL85-45	Cessna Owner Advisory Service	10/11/1985	Informational	Provides Application Form
SNL85-39	Magneto 'P' Lead Nut Torque	08/23/1985	Informational	Applies To Aircraft With Slick Magnetos Only

Pub No.	Pub Name	Date	Compliance	Title Description
SNL85-35R1	Use Of Airplane Lights For Daytime Recognition	08/23/1985	Informational	FAA Safety Program 'Operation Lights On'
SNL85-34	Proper Engine Break-in Procedure	08/09/1985	Informational	TCM Bulletin M81-5, Lycoming Service Instruction 1427A
SE84-09R2	Rubber Fuel Cell Drain Valve Relocation	07/05/1985	See Publication	Modification To Reduce Fuel Cell Wrinkles Or Folds
SNL85-24	Alternator/regulator Troubleshooting Maintenance	05/31/1985	Informational	Helps Determine Cause Of Fluctuating Alternator Output
AK182-199F	Title: Strobe Light Installation - 24 Volt	04/11/1985	Not Applicable	Title: Strobe Light Installation - 24 Volt
SNL85-17	Induction Air Filter Replacement (AD 84-26-02)	03/29/1985	Informational	Paper Type Air Filters - Replace Every 500 Hours
SNL85-13	Improved Flashing Beacon Bulbs	03/22/1985	Informational	New P/N C17312-1 Bulb Available
AK182-217J	Stabilizer Abrasion Boot Installation	03/11/1985	Not Applicable	Stabilizer Abrasion Boot Installation
SNL85-08	Oil Leak Troubleshooting Maintenance Tip	02/15/1985	Informational	Use Of Dye Penetrant Developer
SNL85-01	New Cessna Service Information System	01/18/1985	Informational	New Service Bulletin, Service Newsletter & Ssn Categories
SE84-23	Low Vacuum Warning Light Installation	12/14/1984	Optional	Automatically Illuminates When Suction Drops
SK172-87	Low Vacuum Warning Light Installation - 12 & 24 V	12/14/1984	Not Applicable	Low Vacuum Warning Light Installation - 12 & 24 Volt
SE84-22	Aileron Hinge Assembly Improvement	11/30/1984	Optional	Features A Screw To Secure Hinge Pin In Position
SE84-21	Nose Wheel Shimmy Troubleshooting	11/09/1984	Optional	Additional Maintenance Tips
SE84-19	Instrument Light Dimming Circuit Troubleshooting	10/26/1984	Optional	S.E. Aircraft That Use Transistorized Dimming Circuit
NL84-18	Slick Magneto Servicing Interval	10/26/1984	Informational	100 Hour And 500 Hour Service Requirements

Pub No.	Pub Name	Date	Compliance	Title Description
SE84-15R1	Shimmy Dampener Installation Improvement	10/05/1984	Optional	Provides Thicker Clamp, Larger Locator Pin & Barrel Change
NL84-05	Static Wick Improvement	06/15/1984	Informational	Two-piece Design Allows Wick Replace. Without Removing Base
SK182-83	Shimmy Dampener Clamp Replacement	05/04/1984	Not Applicable	Shimmy Dampener Clamp Replacement
SK310-32D	Oxygen Refill Kit-Less Bottles	04/04/1984	Not Applicable	Oxygen Refill Kit-Less Bottles
SK172-1F	Seals and Lock Rings - Nose Wheel Struts	03/26/1984	Not Applicable	Seals and Lock Rings - Nose Wheel Struts
SK206-25	LH fuel cell drain modification	03/15/1984	Not Applicable	LH fuel cell drain modification
SK206-24	RH fuel cell drain modification	03/15/1984	Not Applicable	RH fuel cell drain modification
SK206-27	LH Fuel Cell Drain Modification	03/15/1984	Not Applicable	LH Fuel Cell Drain Modification
SK206-28	RH Fuel Cell Drain Modification	02/22/1984	Not Applicable	RH Fuel Cell Drain Modification
SK206-23A	Lower LH Wing Panel Modification - Fuel Cell Drain	02/08/1984	Not Applicable	Lower LH Wing Panel Modification - Fuel Cell Drain
SK206-22A	Lower RH Wing Panel Modification - Fuel Cell Drain	02/08/1984	Not Applicable	Lower RH Wing Panel Modification - Fuel Cell Drain
SE84-04	Rubber Fuel Cell Inspection	02/03/1984	See Publication	Check For Wrinkles Or Folds
SE84-03	Nose Gear Actuator Spring Guide Improvement	01/13/1984	Recommended	Provides Steel Spring Guide - Improved Service Life
SE84-02	Maint Procedures To Reduce Valve Sticking In Lyc	01/06/1984	Recommended	Lycoming Service Instruction 1425
AK182-190J	Static Dischargers (Set of 10)	12/08/1983	Not Applicable	Static Dischargers (Set of 10)
SE83-27	Landing Gear Powerpack Grounding Improvement	09/16/1983	See Publication	Improved Grounding For Newer Anodized Powerpack Cases
SE83-25	Main Gear Downlock Switch Improvement	09/09/1983	See Publication	Permits Relocation Of Switch For Improved Reliability/life

Pub No.	Pub Name	Date	Compliance	Title Description
NL83-19	Windshield Sealant Kit - Nonpressurized Aircraft	09/02/1983	Informational	Contains Sealant, Applicators And Instructions Only (TMK01)
SK182-58B	Shimmy Dampener Attach Modification	09/01/1983	Not Applicable	Shimmy Dampener Attach Modification
SK182-57B	Starter Contactor Modification	05/17/1983	Not Applicable	Starter Contactor Modification
SE83-10	Oxygen Bottle Bracket Improvement	04/29/1983	Optional	Heavier Constructed Bracket/improved Service Life
SE83-06	Seat Rail Inspection Guidelines - (AD87-20-03R1)	03/11/1983	Recommended	All S.E. Models Using Extruded Beam Type Seat Rails
SK210-109	95 Amp Alternator Fan & Pulley Replacement	03/01/1983	Not Applicable	95 Amp Alternator Fan & Pulley Replacement
AK182-206E	Electric Elevator Trim Installation - 24 Volt	02/11/1983	Not Applicable	Electric Elevator Trim Installation - 24 Volt
AK182-196D	Cessna Economy Mixture (EGT) Indicator	02/07/1983	Not Applicable	Cessna Economy Mixture (EGT) Indicator Installation
AK182-202D	Hourmeter Installation - 24 Volts	02/04/1983	Not Applicable	Hourmeter Installation - 24 Volts
AK182-205C	Child's Seat Installation	02/04/1983	Not Applicable	Child's Seat Installation
SE82-37R1	Nose Gear Steering Pivot Bolts	12/23/1982	Mandatory	Revised Instructions For Correcting Loose Pivot Bolts
NL82-13	Dorne & Margolin Elt Battery Packs	12/03/1982	Informational	Dorne & Margolin Bulletin DM 254 Attached
SE82-43	Pilot And Copilot Seat Belt Modification	11/05/1982	See Publication	Special Shortener To Prevent Inadvertent Loosening Of Belt
SK172-76	Seat Belt Modification - Shortening	11/05/1982	Not Applicable	Seat Belt Modification - Shortening
SE82-40	Bendix D2000 Series Magneto Distributor Gear Insp	10/08/1982	See Publication	Inspection Per Lycoming SB #461 - (AD82-11-05)
SE82-39	Bendix Magneto Impulse Coupling Flyweight Inspect	10/01/1982	Mandatory	Inspect Magnetos With Less Than 300 Operating Hours

Pub No.	Pub Name	Date	Compliance	Title Description
SE82-36	Fuel Contamination	07/30/1982	Mandatory	Stresses Importance Of Routine Fuel System Inspec. & Maint.
SE82-33	Warning Against Use Of Automotive Gasoline	07/23/1982	Recommended	All SE A/C Originally Certified For Operation w/100 Octane
SE82-34	Flush Fuel Cap Sealing Test Procedure	07/23/1982	Recommended	Identify And Isolate Areas Of Leakage/ensure Proper Sealing
SE82-25	Side Panel Circuit Breaker Insulation	07/02/1982	Recommended	Information Concerning Installation Of Insulator Plate
NL82-09	Vacuum Distribution System Troubleshooting	05/21/1982	Informational	Announces Airborne 343 Test Box & Troubleshooting Procedures
SE82-15	Prop Governor Control Routing	04/16/1982	See Publication	Provides More Direct Routing Of Prop Control
SK182-75A	Prop Governor Control Routing	03/05/1982	Not Applicable	Prop Governor Control Routing
SE82-08	Vacuum System Maintenance Procedures	02/22/1982	Recommended	To Review Vacuum System Maintenance Procedures
SE82-05	Battery Box Drain Tube Inspection	02/01/1982	See Publication	To Prevent Possible Leakage Of Electrolyte From Battery Box
SE81-43	Auxiliary Fuel Pump Cooling	11/02/1981	See Publication	Additional Cooling Using Shroud And Ram Air Ducting
SK182-73	R182 Auxiliary Fuel Pump Cooling Shroud Installat	09/16/1981	Not Applicable	R182 Auxiliary Fuel Pump Cooling Shroud Installation
NL81-05	Goodyear Tire/Wheel Balancer	06/05/1981	Informational	Brochure Describes New Goodyear Tire/wheel Balancer
SE81-20	Engine Baffle/oil Cooler Support Inspection	05/11/1981	See Publication	Provides Detailed Information
AK182-210A	Carburetor Air Temperature Installation - 24 Volt	05/06/1981	Not Applicable	Carburetor Air Temperature Installation - 24 Volt
SE81-18	Nose Gear Tunnel Access Hole Plug Button	04/27/1981	See Publication	One-time Inspection To Ensure Plug Button Installed & Sealed
SK182-67B	Combination Fuel Pressure and Manifold Pressure G	04/07/1981	Not Applicable	Combination Fuel Pressure and Manifold Pressure Gage Installation
SE80-96R1	Oil Cooler Inspection	01/12/1981	See Publication	Stewart Warner Oil Cooler Inspection/replacement

Pub No.	Pub Name	Date	Compliance	Title Description
SE80-87	Fuel Contamination	10/27/1980	See Publication	Procedures To Discover, Remove, And/or Prevent Contamination
SE80-77	Combination Fuel Pressure/ manifold Pressure Gauge	08/11/1980	See Publication	Improves Fuel Pressure Indications
SE79-27R1	R182 Governor Flyweight Assembly Replacement	07/28/1980	See Publication	McCAULEY SERVICE BULLETIN 134A ATTACHED
SE79-48R1S1	Magneto Housing Inspect. & Coil Retention (D2000)	06/30/1980	See Publication	Credit Program Dates Established
SE80-59	Sealing Of Flush Type Fuel Caps	06/23/1980	See Publication	Fuel Cap Alignment Placard
SE80-59S1	Sealing Of Flush Type Fuel Caps	06/23/1980	See Publication	Installation And Maintenance Procedures
SE80-67	Shimmy Dampener Attach Modification	06/23/1980	See Publication	To Strengthen Shimmy Dampener Installation
NL80-09	Volcanic Ash Hazard (FAA Advisory Circular)	06/06/1980	Informational	AC No. 43-16 'Volcanic Ash Hazard'
SE80-58	Improved Window And Windshield Sealer	05/27/1980	See Publication	Improved Sealer (Isocryl 5603) Now Being Used
SE80-52	Flashing Beacon Power Supply	05/12/1980	See Publication	Instructions For Power Supply Testing And Replacement
SE80-53	Flashing Beacon Bulb	05/12/1980	See Publication	Improved Service Life By Repositioning Bulb And Socket
AK182-207B	Cessna 200A Nav-O-Matic (Type AF-295B) Autopilot	05/02/1980	Not Applicable	Cessna 200A Nav-O-Matic (Type AF-295B) Autopilot Installation - 24 Volt
SE80-25	Oil Level Dipstick Replacement Kit	03/10/1980	See Publication	Lycoming S.I. Number 1379 Announces LW-16517 Kit
SE80-16	Turnbuckle Barrel Inspection	02/04/1980	See Publication	One-time Visual Inspection For Apparent Cracks
SE80-15	Wing Leading Edge Root Rib Sealing	02/04/1980	See Publication	Provide Maximum Cabin Comfort During Cold Weather Operation
SE80-17	Hydraulic Motor Brushes	02/04/1980	See Publication	Provide Increased Motor Service Life
NL80-02	Passenger Briefing Cards	02/01/1980	Informational	Designed To Assist Part 135 Operators

Pub No.	Pub Name	Date	Compliance	Title Description
SE80-5	Nosecap Reinforcement	01/21/1980	See Publication	Reduced Vibration Transmission And Improved Cabin Comfort
SE79-48R1	Magneto Housing Inspect. & Coil Retention (D2000)	01/21/1980	See Publication	Lycoming Service Bulletin #438A/Bendix #605A Attached
SE80-04	24 Volt Batteries	01/21/1980	See Publication	Proper Charging And Servicing Of 24-volt Lead Acid Batteries
SK182-61A	Wing Leading Edge Root Rib Sealing	01/10/1980	See Publication	Wing Leading Edge Root Rib Sealing
SK182-59B	Nosecap Reinforcement - R182 & FR182	01/07/1980	See Publication	Nosecap Reinforcement - R182 & FR182
SE79-63	Starter Contactors	12/17/1979	See Publication	Heavy Duty Contactor Uses Cadmium Oxide Coated Points
SE79-55	Prop Governor Control Mounting Bracket	11/19/1979	See Publication	New Bracket Provides Increased Adjustment Capabilities
AK182-208A	Cessna 300A Nav-O-Matic (Type AF-395A) Autopilot	09/28/1979	Not Applicable	Cessna 300A Nav-O-Matic (Type AF-395A) Autopilot Installation - 24 Volt
SE78-67R1	Oil Quick Drain Valve	09/04/1979	See Publication	Clarifies Valve Usage And Applicable Airplanes
AK182-198A	Ground Service Receptacle Installation - 24 Volt	08/20/1979	Not Applicable	Ground Service Receptacle Installation - 24 Volt
AK182-191G	Aft Air Vent Installation	08/15/1979	Not Applicable	Aft Air Vent Installation
AK172-182E	Detector - Standard Navigation Lights (Rod Type)	07/02/1979	Not Applicable	Detector - Standard Navigation Lights (Rod Type)
SE79-30	Use Of Fuel Additives For Cold Weather Operation	06/18/1979	See Publication	Cold Weather Operation Procedures Attached
SE79-06	Engine Control Attachment	04/16/1979	See Publication	Improved Attachment For Throttle, Mixture & Prop Controls
SE79-08	Operation Blue Ribbon - Use of TCP as Fuel Add	03/19/1979	See Publication	Lycoming Service Letter No. 190 Attached
SE79-09	Operating Procedures To Reduce Lead Fouling	03/19/1979	See Publication	Lycoming Service Letter No. L-192 Attached

Pub No.	Pub Name	Date	Compliance	Title Description
SNL78-09	Plastic Envelope For Aircraft Weight And Balance	12/22/1978	Informational	Convenient Place To Keep Important Papers
SE78-44S1	Magneto Rear Bearing Inspection	11/13/1978	See Publication	Adds Reims Airplanes And Credit Cutoff Date
SK185-20	Dorne & Margolin ELT Modification Kit	11/01/1978	Not Applicable	Dorne & Margolin ELT Modification Kit
SK182-53B	Avionics Cooling Installation	10/30/1978	Not Applicable	Avionics Cooling Installation
SE78-44	Magneto Rear Bearing Inspection	07/03/1978	See Publication	Inspect For Tight Bearing And Replace If Required
SE78-37	Steering Bungee Boot Inspection	06/05/1978	See Publication	Inspect For Proper Boot Installation
SNL77-10	Cessna Regulator And Alternator Field Tester	11/18/1977	Informational	P/N 9870000-1 Text Box Available
AK182-203	Cessna 200A Nav-O-Matic (Type AF-295B) Autopilot	06/30/1977	Not Applicable	Cessna 200A Nav-O-Matic (Type AF-295B) Autopilot Installation - 24 Volt
AK182-204	Cessna 300A Nav-O-Matic (Type Af-395A) Autopilot	06/30/1977	Not Applicable	Cessna 300A Nav-O-Matic (Type Af-395A) Autopilot Installation - 24 Volt
AK182-200A	Winterization	08/21/1976	Not Applicable	Winterization
SK421-68D	Hydro Modification (Model SE589 and Model SE588 M	05/07/1976	Not Applicable	Hydro Modification (Model SE589 and Model SE588 Modified with Service Kit SK210-38)
SK150-20A	Wheel Balancer	12/16/1974	Not Applicable	Wheel Balancer
AK205-117B	VHF Antenna Installation	06/19/1969	Not Applicable	VHF Antenna Installation
SK182-43	Cylinder Head Temperature Gage Calibration Unit	01/28/1969	Not Applicable	Cylinder Head Temperature Gage Calibration Unit
AK205-81E	Cessna 300 Series Radio Installation Kit	01/11/1967	Not Applicable	Cessna 300 Series Radio Installation Kit (Includes Nav/Com 300R & Transceiver 300)
AK172-124	Cessna DME 300 Installation Kit (14&28-V Aircraft)	01/09/1967	Not Applicable	Cessna DME 300 Installation Kit (14&28-V Aircraft)
SK150-22	Diode Installation - Rotating Beacon (12 Volt)	03/29/1966	Not Applicable	Diode Installation - Rotating Beacon (12 Volt)